

# Acceptable Tolerance for Simulated Divided Lites (SDLs)

Photos show an acceptable tolerance in SDL fit.

Front View



Angled View



SDLs may or may not touch the opposing frame surfaces.

An opening gap from 1/32" to 3/32" between the frame and the cut ends of one or both SDLs is an acceptable tolerance. The opening gap can vary on either SDL end and may vary between individual SDLs on the same window.



3000 North Township Boulevard  
Pittston, PA 18640  
800-338-9997  
[www.interstatebldg.com](http://www.interstatebldg.com)